

Abstract

A method is provided for establishing an electrical connection between at least one connecting piece of a workpiece and at least one wire. Firstly the end of the at least one wire is prepared. Then the prepared end of the at least one wire is positioned on the terminal or connecting piece of the workpiece. Thereafter the at least one connecting piece and the prepared end of the at least one wire are welded together by laser radiation.